

IEEE Std 142<sup>™</sup>-1991

(Revision of IEEE Std 142-1982)

## Errata to IEEE Recommended Practice for Grounding of Industrial and Commercial Power Systems

Sponsor

**Power System Engineering Committee** 

of the

**IEEE Industry Applications Society** 

Correction Sheet Issued 22 March 2006

Copyright © 2006 by the Institute of Electrical and Electronics Engineers, Inc. All rights reserved. Published 2006. Printed in the United States of America.

This correction sheet may be freely reproduced and distributed in order to maintain the utility and currency of the underlying Standard. This correction sheet may not be sold, licensed or otherwise distributed for any commercial purposes whatsoever. The content of this correction sheet may not be modified.

## Page ii, The first paragraph, should be changed to read as follows:

This edition incorporates corrections to minor typographical errors. In several cases, typographical errors in the original text could lead to misinterpretation. Changes of this type are indicated in the text by a change bar running in the left margin next to the corrected line in the text. This occurs on pages 5, 7, 10, 56, 99, 129, 133, and 134.

22 March 2006 SH14498