

Verilan Network Provider Update

March, 2018

IEEE 802 Plenary

Hyatt Regency O'Hare, Rosemont, IL, USA



Outage

The image shows two network switches stacked vertically. The top switch is a Catalyst 3500 series PoE-24. The bottom switch is a Catalyst 3500 series PoE-24. Large blue text is overlaid on the image, reading: "BPDU's Wrong", "Switch Port:", "Error/Disable", and "Hotel Fixed VLAN".

BPDU's Wrong
Switch Port:
Error/Disable
Hotel Fixed VLAN

HDMI

A photograph showing a variety of HDMI-related hardware items laid out on a dark blue surface. The items include several black HDMI cables of different lengths, some with gold-plated connectors, and various dongles and adapters. Some are in their original retail packaging, which includes yellow boxes and clear plastic bags. One yellow box is labeled 'USB 3.0 TC' and '\$20'. Another yellow box is labeled '\$15'. A clear plastic bag is labeled 'VCE' and 'HDMI to USB 3.0 Adapter Cable/Adaptors'. The text 'Form Factors? Many. High Definition? Yes, Please So many dongles' is overlaid in large, bold, blue letters across the image.

**Form Factors?
Many.
High Definition?
Yes, Please
So many dongles**



Spent Monday



Morning

Breathing Life to Old



Laptops

He's not Dead Yet,

Jim

DHCP records report



700 Guests
1600 Devices
We're travelling light

802.11n Cisco 1142 firmware
upgrade vs Intel Wireless HT mode

Spectrum Spreading Removes Connectivity Interop Issue



Total Bandwidth
Attendees'
Bandwidth
Not even close to
matching
Cut LOLcats
downloads

90-second empty ballroom
disconnect 11pm Thursday

**Double-checking
ports**

**Means never having
to say**

You're sorry. Oops.

Fixed.



HDMI